

Model	No. of Cyl.	Std. Bore x Stroke (mm)	Displ. (cc)	Bore Size (mm)	Wiseco Kit Part No.	Price Per Kit	Wiseco Piston Part No.	Price Per Piston
440 Cheetah 1972-75 El Tigre EXT & EXT Special 440 1971 Lynx II 440 1974 Pantera 440 1975 Panther 440 1971-7 5 Puma 440 1971-73 Puma Mod 440A 1971 T1A440F2 T1A440S1 T1B440S T7A440RX T7C440FR2 VIP440 1974  • Pro-Lite • Chrome Bore - 2677CDM rings req'd for Std. Bore • Sleeving or replating required for oversizes.	2	68 x 60	436	Std. 0.25 0.50 1.00			2084M06800 2084M06825 2084M06850 2084M06900	\$99.37 (D1416)
Lynx 2000S 1977-80  • Nikasil Bore • Sleeving or replating required for oversizes	1	70 x 65	250	Std.			2286M07000	\$98.93 (D6395)
440 El Tigre 4000 1976 Bearcat 440 1993-98 Bearcat 440 I, II 1999-00 Jag AFS 1989-93 Jag 440 1987-99 Jag 440 Deluxe 1999 Jag 4000 1981-85 Panther 440 1980-81, 1984, 1989-90 Panther 440 1993-01 Super Jag 1987-97 Trailcat 4000 1980-81 Z440 1995-98  • Nikasil Bore Note: Will not fit Z440 or Z440 Snow Pro 1999-02	2	65 x 65	431	Std.			2300M06500	\$94.45 (D7665)
440LC 1976-80 6000 Series 1976-79 El Tigre 5000 1987-88 Pantera 1985-90  • Nikasil Bore	2	68 x 60	435	Std.	SK1000	\$252.97 (D87151)	2268M06800	\$94.45 (D7665)
440Z 1993 Cheetah Touring 1991-94 Cougar 1991-94 Jag 440 LC 1996 Pantera 440 1992-93 Panther 440 LC 1996-97 Prowler 440 LC 1990-94 Prowler Special LC 1991-94 ZL440 1997-00 ZR440 1994-95  • Nikasil Bore • Pro-Lite	2	68 x 60	436	Std.	SK1085	\$239.07 (D44341)	2332M06800	\$96.05 (D4673)
ZR 440 1996-97 ZR440 1998 (Consumer model)  • Nikasil Bore • Pro-Lite	2	66.5 x 63	438	Std.	SK1260	\$279.83 (D09761)	2390M06650	\$105.87 (D2536)
ZR 440 Snow Pro 1998-01  • Nikasil Bore • Pro-Lite	2	66.5 x 63	438	Std.	SK1308	\$289.91 (D59371)	2418M06650	\$112.02 (D1276)
ZR 440 Sno Pro 2002-03  • Nikasil Bore • Pro-Lite • Electra Coated	2	66.5 x 63	438	Std.	SK1331	\$340.42 (D52402)	2439M06650	\$129.98 (D9977)

Repl Ring Set Part No.	Repl Piston Pin	Repl Retainer Clips	Top End Gasket Kit	Bottom End Gasket Kit w / Seals	Top End Bearing	Main Bearing L.H. PTO	Main Bearing L.H. Ctr.	Main Bearing R.H. Ctr.	Main Bearing R.H. Mag	Advanced Sleeve	LA Sleeve
2677CDM 2687CD 2697CD 2717CD \$27.95 (D7761)	S259 \$13.60 (D618)	CW16 \$2.00 (D021)	W5311 \$48.27 (D6982)		B1021 \$14.95 (D798)	B5017 \$35.96 (D8512)			B5017 \$35.96 (D8512)		
1974-75 Cheetah, Panther (needs 2)  1975 Pantera (needs 2)  B5002 El Tigre \$11.45 (D786)											1974-75 Cheetah, Panther  1975 Pantera  B5002 El Tigre \$11.45 (D786)
2756CD \$27.95 (D7761)	S513 \$13.60 (D618)	CW18 \$2.00 (D021)	W5090 \$34.03 (D2402)		B1014 \$15.95 (D759)						
2559CD \$27.95 (D7761)	S486 \$13.60 (D618)	CW16 \$2.00 (D021)			B1008 \$14.95 (D798)		TBA	TBA			
2677CD \$27.95 (D7761)	S513 \$13.60 (D618)	CW18 \$2.00 (D021)	W5092 \$48.27 (D6982)		B1014 \$15.95 (D759)		TBA	TBA	TBA		
2677CD \$27.95 (D7761)	S513 \$13.60 (D618)	CW18 \$2.00 (D021)	W5213 \$46.97 (D8182)	WB1102 \$17.89 (D3701)	B1014 \$15.95 (D759)	TBA			TBA		
2618CD \$27.95 (D7761)	S511 \$13.60 (D618)	CW18 \$2.00 (D021)	W5596 \$68.09 (D6804)	WB1106 \$24.04 (D2441)	B1014 \$15.95 (D759)	TBA	TBA	TBA	TBA		
2618CD \$27.95 (D7761)	S511 \$13.60 (D618)	CW18 \$2.00 (D021)	W5951 1999-01 \$68.09 (D5804)	WB1106 \$24.04 (D2441)	B1014 \$15.95 (D759)	TBA	TBA	TBA	TBA		
6650KF \$16.95 (D7101)	S391 \$13.60 (D618)	CW18 \$2.00 (D021)	W6199 2002-05 \$80.46 (D8284)	WB1110 \$51.57 (D4903)							
											Teflon seals

Model	No. of Cyl.	Std. Bore x Stroke (mm)	Displ. (cc)	Bore Size (mm)	Wiseco Kit Part No.	Price Per Kit	Wiseco Piston Part No.	Price Per Piston
5000 El Tigre Cheetah 5000 1976-78, 1986-90 Cougar 5000 1985-90 Pantera 1976-81 Panther 5000 1976-79  • Nikasil Bore	2	70 x 65	499	Std.			2286M07000	\$98.93 (D6395)
Powder Special 500 EFI 2000 ZL500 Series 1998-00 ZR500 1998-00  • A Case Series • Nikasil Bore • Pro-Lite	2	71 x 62.7	497	Std.	SK1261	\$279.89 (D39761)	2393M07100	\$106.96 (D8146)
6000 Series LC 1980-81, 1984-85  • Nikasil Bore • Pro-Lite	2	70 x 65	499	Std.			2293M07000	\$98.93 (D6395)
F5 Fire Cat 2003-08 F5 Fire Cat Sno Pro 2004-06 F5 LXR 2008 M5 2005 M5 2006 EFI Sabercat 500 LX 2004-06 Sabercat 500 2004-06 Crossfire 2007-08 T500 2008  • Nikasil Bore • Pro-Lite	2	71 x 63	499	Std.	SK1330	\$318.57 (D41191)	2438M07100	\$123.53 (D2147)
Cheetah 530 LC 1986-88 530 El Tigre 530 EXT 1989-90 El Tigre 6000 LC 1986-90  • Nikasil Bore • Pro-Lite	2	72 x 65	529	Std.	SK1003	\$246.59 (D59741)	2314M07200	\$99.16 (D9495)
Bearcat LC 1995-02 Cheetah 550 1994 Cougar 1995-98 EXT 550 1992-93 EXT EFI 1993-94 EXT Mountain Cat EXT Special 1991 Pantera 550 2004-05 Pantera 550 EFI 2003 Pantera EFI 1993-94 Panther 1997-01 Prowler Two Up 1995 ZL550 2001-02 ZL550 ESR 2000-03  • Nikasil Bore • Pro-Lite	2	73.4 x 65	550	Std.	SK1101	\$282.07 (D42961)	2338M07340	\$106.99 (D0246)
EFI 1998 EXT 1996-98 EXT 580 Mountain Cat 1993 EXT 580Z 1993-94 EXT 580Z LC 1993-97 EXT Deluxe 1996-98 Pantera 1996-98, 2001 Pantera 580 EFI 1999-01 Powder Special 1996 ZR580 1993-97  • Pro-Lite • Nikasil Bore • Sleeving or replating required for oversizes	2	75.4 x 65	581	Std. 1.00	SK1141 SK1184	\$285.75 (D54171) \$307.53 (D25481)	2348M07540 2348M07640	\$108.83 (D0356) \$119.72 (D3817)

Repl Ring Set Part No.	Repl Piston Pin	Repl Retainer Clips	Top End Gasket Kit	Bottom End Gasket Kit w / Seals	Top End Bearing	Main Bearing L.H. PTO	Main Bearing L.H. Ctr.	Main Bearing R.H. Ctr.	Main Bearing R.H. Mag	Advanced Sleeve	LA Sleeve
2756CD \$27.95 (D7761)	S513 \$13.60 (D618)	CW18 \$2.00 (D021)	W5090 \$34.03 (D2402)		B1014 \$15.95 (D759)	TBA	TBA	TBA	TBA		
2795KD \$29.95 (D7971)	S512 \$13.60 (D618)	CW20 \$2.00 (D021)	W5597 \$68.09 (D5804)	WB1106 \$24.04 (D2441)	B1024 \$15.95 (D759)	TBA	TBA	TBA			
2756CD \$27.95 (D7761)	S513 \$13.60 (D618)	CW18 \$2.00 (D021)	W5092 \$48.27 (D6982)								FL1105 \$95.20 (D2175)
2795KD \$14.98 (D998)	S419 \$13.60 (D618)	CW22 \$2.00 (D021)	W6200 2004-07 \$71.51 (D1924)	WB1110 \$51.57 (D4903) <i>Teflon seals</i>							
2835CD \$27.95 (D7761)	S511 \$13.60 (D618)	CW18 \$2.00 (D021)	W5037 \$48.27 (D6982)								
2889CDW \$27.95 (D7761)	S512 \$13.60 (D618)	CW20 \$2.00 (D021)	W5245 \$68.09 (D5804)	WB1106 \$24.04 (D2441)	B1024 \$15.95 (D759)	TBA	TBA	TBA	TBA		6013FA \$105.56 (D4336)
2966TDW 3012TDW \$28.94 (D6371)	S512 \$13.60 (D618)	CW20 \$2.00 (D021)	W5334 \$68.09 (D6504)	WB1106 \$24.04 (D2441)	B1024 \$15.95 (D759)	TBA			TBA		

Model	No. of Cyl.	Std. Bore x Stroke (mm)	Displ. (cc)	Bore Size (mm)	Wiseco Kit Part No.	Price Per Kit	Wiseco Piston Part No.	Price Per Piston
Powder Special 1998-00 Powder Special EFI 1998-99 ZR600 1998-99 ZR600 EFI 1998-99 ZL600 1998-99 ZL600 EFI 1998-99	2	78 x 67	599	Std. 0.50 1.00	SK1236 SK1357 SK1358	\$311.23 (D47681)	2391M07800 2391M07850 2391M07900	\$114.94 (D6986)
• A Case Series • Nikasil Bore • Pro-Lite								
OVERBORE to 680cc for: Powder Special 1998-00 Powder Special EFI 1998-99 ZR600 1998-99 ZR600 EFI 1998-99 ZL600 1998-99 ZL600 EFI 1998-99	2	78 x 62.7	680	5.00	SK1264	\$315.15 (D90981)	2392M08300	\$123.53 (D2147)
• A Case Series • Nikasil Bore • Pro-Lite • Cylinder sleeving required • Cylinder head machining required								
Mountain Cat 2001 Mountain Cat 600 EFI LE 2001-04 Pantera 600 EFI 2002-05 Powder Special 600 EFT 2000 ZL 600 EFI Series 2000-03 ZR 600 2000-02 ZR 600 EFI LE 2001 ZR 600 CCE EFI 2002	2	78 x 62.7	599	Std.	SK1316	\$306.11 (D76381)	2427M07800	\$120.01 (D2127)
• B Case Series • Pro-Lite • Electra Coated								
OVERBORE to 680cc for: Mountain Cat 2001 Mountain Cat 600 EFI LE 2001-04 Pantera 600 EFI 2002-05 Powder Special 600 EFT 2000 ZL 600 EFI Series 2000-03 ZR 600 2000-02 ZR 600 EFI LE 2001 ZR 600 CCE EFI 2002	2	78 x 62.7	680	5.00	SK1317	\$316.23 (D47981)	2425M08300	\$124.07 (D4447)
• B Case Series • Pro-Lite • Electra Coated • Cylinder sleeving or replating required • Cylinder Head machining required								
EXT Triple 600 1996-97 EXT Triple Touring 1997-98 Powder Extreme 1998 Triple Touring 600 1999-00 ZRT600 1996-00	3	66.5 x 57	594 603 612	Std. 0.50 1.00	SK1189 SK1350 SK1351	\$462.68 (D16772)	2364M06650 2364M06700 2364M06750	\$104.29 (D8526)
• Nikasil Bore • Pro-Lite								
OVERBORE to 696cc for: EXT Triple 600 Series 1996-98 Powder Extreme 1998 Triple Touring 600 1999-00 ZRT600 1996-00	3	66.5 x 57	696	5.50	SK1194	\$386.11 (D76132)	2369M07200	\$101.08 (D5606)
• Nikasil Bore • Pro-Lite • Cylinder sleeving required • Cylinder Head machining required								
Crossfire 6 2006-07 F6 Fire Cat Series 2004-08 F6 Fire Cat EFI Sno Pro 2004-08 M6 Series 2005-08 Saber Cat 600 Series 2004-06 F6 LXR 2008	2	73.8 x 70	599	Std.	TBA		2445M07380	\$134.97 (D8908)
• Nikasil Bore • Electra Coated								

Repl Ring Set Part No.	Repl Piston Pin	Repl Retainer Clips	Top End Gasket Kit	Bottom End Gasket Kit w / Seals	Top End Bearing	Main Bearing L.H. PTO	Main Bearing L.H. Ctr.	Main Bearing R.H. Ctr.	Main Bearing R.H. Mag	Advanced Sleeve	LA Sleeve
3071KD 3091KD 3110KD \$29.95 (D7971)	S512 \$13.60 (D618)	CW20 \$2.00 (D021)	W5961 \$68.09 (D5804)	WB1106 \$24.04 (D2441)	B1024 \$15.95 (D759)	TBA	TBA	TBA	TBA	6054FA \$105.56 (D4336)	FL1235 \$95.20 (D2175)
3268KD \$29.95 (D7971)	S512 \$13.60 (D618)	CW20 \$2.00 (D021)	W5961 \$68.09 (D5804)	WB1106 \$24.04 (D2441)	B1024 \$15.95 (D759)	TBA	TBA	TBA	TBA	6054FB \$132.13 (D8297)	FL1235B \$110.50 (D0366)
3071KD \$29.95 (D7971)	S640 \$13.60 (D618)	CW22 \$2.00 (D021)	W5961 \$68.09 (D5804)	WB1108 \$23.46 (D8041)	TBA	TBA					
3268KD \$29.95 (D7971)	S640 \$13.60 (D618)	CW22 \$2.00 (D021)	W5961 \$68.09 (D6804)	WB1108 \$23.46 (D8041)	TBA	TBA					
2618CD 2638CD 2658CD \$27.95 (D7761)	S511 \$13.60 (D618)	CW18 \$2.00 (D021)	W5498 \$82.87 (D2794)	WB1101 \$35.96 (D8512)  Teflon PTO seal	B1014 \$15.95 (D759)	TBA	TBA	TBA		6026FA \$105.56 (D4336)	FL1212 \$95.20 (D2175)
2835CD \$27.95 (D7761)	S513 \$13.60 (D618)	CW18 \$2.00 (D021)	W5553 \$82.87 (D2794)	WB1101 \$35.96 (D8512)  Teflon PTO seal	B1014 \$15.95 (D759)	TBA	TBA	TBA		6026FB \$132.13 (D8297)	
2905KD \$29.95 (D7971)	S694 \$13.60 (D618)	CW22 \$2.00 (D021)	W6161 \$71.51 (D1924)	WB1109 \$58.07 (D4843)  Teflon seals	TBA						

Model	No. of Cyl.	Std. Bore x Stroke (mm)	Displ. (cc)	Bore Size (mm)	Wiseco Kit Part No.	Price Per Kit	Wiseco Piston Part No.	Price Per Piston
<b>Wild Cat 650 1988-90</b> <ul style="list-style-type: none"> <li>Nikasil Bore</li> <li>Pro-Lite</li> <li>Sleeving or replating required for oversizes</li> </ul>	2	78 x 68	650	Std. 3.00 3.50	<b>SK1054</b> <b>SK1195</b> <b>SK1354</b>	\$277.96 (D87661) \$296.19 (D17771)	<b>2323M07800</b> <b>2370M08100</b> <b>2370M08150</b>	\$103.23 (D4916) \$113.46 (D8086)
<b>Crossfire 7 2006</b> <b>F7 Firecat Series 2003-06</b> <b>F7 Firecat Sno-Pro Series 2004-06</b> <b>M7 Series 2005-06</b> <b>Sabercat 700 EFI Series 2004-06</b> <ul style="list-style-type: none"> <li>Nikasil Bore</li> <li>Pro-Lite</li> <li>Electra Coated</li> </ul>	2	79.7 x 70	698	Std.	<b>SK1328</b>	\$337.43 (D64202)	<b>2410M07970</b>	\$134.29 (D7508)
<b>Mountain Cat 700 1991-93</b> <b>Mountain Cat 700 EFI 1991-96</b> <b>Powder Special 700 1999-00</b> <b>Wild Cat 700 1991-96</b> <b>ZL700 2000</b> <b>ZR700 1994-96, 1999-00</b> <ul style="list-style-type: none"> <li>Nikasil Bore</li> <li>Pro-Lite</li> <li>Sleeving or replating required for oversizes</li> </ul>	2	81 x 68	699 716	Std. 1.00	<b>SK1195</b> <b>SK1196</b>	\$296.19 (D17771) \$318.65 (D91191)	<b>2370M08100</b> <b>2370M08200</b>	\$113.46 (D8086) \$124.81 (D8847)
<b>OVERBORE to 790cc for:</b> <b>Mountain Cat 700 1991-93</b> <b>Mountain Cat 700 EFI 1991-96</b> <b>Powder Special 700 1999-00</b> <b>Wildcat 700 1991-96</b> <b>ZL700 2000</b> <b>ZR700 1994-96, 1999-00</b> <ul style="list-style-type: none"> <li>Nikasil Bore</li> <li>Pro-Lite</li> <li>Cylinder sleeving or replating required</li> <li>Must bore case to accept sleeves</li> <li>Cylinder Head machining required</li> </ul>	2	81 x 68	790	5.00	<b>SK1273</b>	\$344.87 (D29602)	<b>2400M08600</b>	\$136.68 (D1028)
<b>Pantera 800 1998-99</b> <b>ZRT 800 1995-01</b> <ul style="list-style-type: none"> <li>Nikasil Bore</li> <li>Pro-Lite</li> </ul>	3	72 x 65	794	Std.	<b>SK1176</b>	\$407.38 (D34442)	<b>2361M07200</b>	\$108.17 (D0946)
<b>800cc Twin</b> <b>Mountain Cat 800 LE 2001-04</b> <b>Mountain Cat 800 EFI LE 2002-03</b> <b>Pantera 800 EFI 2003-04</b> <b>ZL 800 Series 2001-03</b> <b>ZR800 Series 2001-03</b> <ul style="list-style-type: none"> <li>Nikasil Bore</li> <li>Pro-Lite</li> <li>Electra Coated</li> </ul>	2	81 x 76	785	Std.	<b>SK1318</b>	\$337.43 (D64202)	<b>2431M08100</b>	\$134.29 (D7508)
<b>OVERBORE to 883cc for:</b> <b>800cc Twin</b> <b>Mountain Cat 800 2001-04</b> <b>Mountain Cat 800 EFI LE 2002-03</b> <b>Pantera 800 EFI 2003-04</b> <b>ZL 800 Series 2001-03</b> <b>ZR800 Series 2001-03</b> <ul style="list-style-type: none"> <li>Nikasil Bore</li> <li>Electra Coated</li> <li>Pro-Lite</li> <li>Cylinder head machining required</li> <li>Sleeving or replating required for oversize</li> </ul>	2	81 x 76	883	5.00	<b>SK1320</b>	\$366.53 (D29912)	<b>2429M08600</b>	\$147.51 (D1588)
<b>F8 Series 2007-08</b> <b>M8 Series 2007-08</b> <b>Crossfire 8 Series 2007-08</b> <ul style="list-style-type: none"> <li>Nikasil Bore</li> <li>Pro-Lite</li> <li>Electra Coated</li> </ul>	2	85 x 70	794	Std.	<b>SK1374</b>	TBA	<b>2451M08500</b>	TBA

Repl Ring Set Part No.	Repl Piston Pin	Repl Retainer Clips	Top End Gasket Kit	Bottom End Gasket Kit w / Seals	Top End Bearing	Main Bearing L.H. PTO	Main Bearing L.H. Ctr.	Main Bearing R.H. Ctr.	Main Bearing R.H. Mag	Advanced Sleeve	LA Sleeve
<b>3071TD</b> <b>3189TDW</b> <b>3209TD</b> \$28.94 (D6371)	<b>S461</b> \$13.60 (D618)	<b>CW20</b> \$2.00 (D021)	<b>W5088</b> \$71.51 (D1924)	<b>WB1103</b> \$30.00 (D0081)	<b>B1024</b> \$15.95 (D759)	TBA					
<b>3140KD</b> \$28.95 (D7371)	<b>S662</b> \$13.60 (D618)	<b>CW22</b> \$2.00 (D021)	<b>W6161</b> \$71.51 (D1924)	<b>WB1109</b> \$58.07 (D4843) <i>Teflon seals</i>	TBA	TBA	TBA	TBA	TBA		
<b>3189TDW</b> <b>3228TD</b> \$28.94 (D6371)	<b>S461</b> \$13.60 (D618)	<b>CW20</b> \$2.00 (D021)	<b>W5088</b> \$71.51 (D1924)	<b>WB1113</b> \$55.18 (D1133) <i>Teflon seals</i>	<b>B1024</b> \$15.95 (D759)	TBA	TBA	TBA	TBA	<b>6002FA</b> Wild Cat Mtn. Cat 1991-96 <b>6056FA</b> ZR700 1994-96, Powder 1999-00 \$108.31 (D9946)	<b>FL1204 ZR700</b> 1994-96 <b>Powder</b> 1999-00 \$110.50 (D0366)
<b>3385KD</b> \$29.95 (D7971)	<b>S423</b> \$13.60 (D618)	<b>CW20</b> \$2.00 (D021)	<b>W5088</b> \$71.51 (D1924)	<b>WB1113</b> \$55.18 (D1133) <i>Teflon seals</i>	<b>B1024</b> \$15.95 (D759)	TBA	TBA	TBA	TBA	<b>6056FB</b> ZR700 1994-96, Powder 1999-00 \$132.13 (D5397)	<b>FL1178B</b> Wild Cat Mtn Cat 1991-96 \$127.50 (D0567)
<b>2835CD</b> \$27.95 (D7761)	<b>S512</b> \$13.60 (D618)	<b>CW20</b> \$2.00 (D021)	<b>W5447</b> \$82.87 (D2794)	<b>WB1105</b> \$32.96 (D8791)	<b>B1024</b> \$15.95 (D759)					<b>6019FA</b> \$105.56 (D4336)	
<b>3189KD</b> \$29.95 (D7371)	<b>S651</b> \$13.60 (D618)	<b>CW24</b> \$2.00 (D021)	<b>W5941</b> \$71.51 (D1924)	<b>WB1107</b> \$27.07 (D4261)	TBA						
<b>3385KD</b> \$29.95 (D7371)	<b>S651</b> \$13.60 (D618)	<b>CW24</b> \$2.00 (D021)	<b>W5941</b> \$71.51 (D1924)	<b>WB1107</b> \$27.07 (D4261)	TBA						
TBA	TBA	TBA	<b>W6588</b> \$109.18 (D1556)	TBA	TBA						

Model	No. of Cyl.	Std. Bore x Stroke (mm)	Displ. (cc)	Bore Size (mm)	Wiseco Kit Part No.	Price Per Kit	Wiseco Piston Part No.	Price Per Piston
King Cat 900 Series 2004-06 Mountain Cat 900 Series 2003-04 ZR900 Series 2003-06 ZR 900 SNO PRO Series 2005-06	2	85 x 76	862	Std.	SK1329	\$337.43 (D64202)	2407M08500	\$134.29 (D7508)
• Nikasil Bore • Pro-Lite • Electra Coated								
Thunder Cat 900 1993-97	3	76.5 x 65	895	Std.	SK1143	\$395.55 (D23732)	2349M07650	\$104.22 (D3526)
• Nikasil Bore • Pro-Lite								
OVERBORE to 992cc for: Thunder Cat 900 1993-97	3	76.5 x 65	992	4.00	SK1185	\$443.98 (D93662)	2349M08050	\$120.37 (D2227)
• Nikasil Bore • Pro-Lite • No cylinder head modification required • Cylinder sleeving or replating required								
OVERBORE to 992cc for: Thunder Cat 900 1993-97	3	76.5 x 65	992	4.00 4.50	SK1276	\$456.16 (D07372)	2403M08050 2403M08100	\$124.43 (D6647)
• Nikasil Bore • Pro-Lite • Cylinder sleeving or replating required • Cylinder Head machining required								
Mountain Cat 1000 1998-02 Pantera 1000 2000-01 Thunder Cat 1000 1998-02	3	81 x 64.6	1000	Std.	SK1265	\$417.43 (D64052)	2394M08100	\$111.52 (D1966)
• Nikasil Bore • Pro-Lite								
OVERBORE to 1098cc for: Mountain Cat 1000 1998-02 Pantera 1000 2000-01 Thunder Cat 1000 1998-02	3	81 x 64.6	1098	4.00	SK1266	\$468.52 (D59082)	718M08500	\$122.34 (D1437)
• Nikasil Bore • Pro-Lite • Cylinder sleeving or replating required • Cylinder Head machining required								
F1000 Series 2007-08 M1000 Series 2007-08 Crossfire 1000 Series 2007-08	2	90.3 x 78	1000	Std.	SK1373	TBA	2450M09030	TBA
• Nikasil Bore • Pro-Lite • Electra Coated								



Individual pistons sold complete with - Rings, piston pins & retainer clips

Repl Ring Set Part No.	Repl Piston Pin	Repl Retainer Clips	Top End Gasket Kit	Bottom End Gasket Kit w / Seals	Top End Bearing	Main Bearing L.H. PTO	Main Bearing L.H. Ctr.	Main Bearing R.H. Ctr.	Main Bearing R.H. Mag	Advanced Sleeve	LA Sleeve
3347KD \$29.95 (D7971)	S651 \$13.60 (D618)	CW24 \$2.00 (D021)	W5941 \$71.51 (D1924)	WB1107 \$27.07 (D4261)	TBA						
3012TDW \$28.94 (D6371)	S512 \$13.60 (D618)	CW20 \$2.00 (D021)	W5335 \$82.87 (D2794)	WB1104 \$31.11 (D6681)	B1024 \$15.95 (D759)					6015FA \$105.56 (D4336)	
3169TD \$28.94 (D6371)	S512 \$13.60 (D618)	CW20 \$2.00 (D021)	W5335 \$82.87 (D2794)	WB1104 \$31.11 (D7681)	B1024 \$15.95 (D759)						FL1191B \$127.50 (D0567)
3169KD 3189KD \$29.95 (D7971)	S423 \$13.60 (D618)	CW20 \$2.00 (D021)	W5335 \$82.87 (D2794)	WB1104 \$31.11 (D7681)	B1024 \$15.95 (D759)						FL1191B \$127.50 (D0567)
3189KD \$29.95 (D7971)	S539 \$13.60 (D618)	CW22 \$2.00 (D021)	W5335 \$82.87 (D2794)	WB1105 \$32.96 (D8791)						6057FA \$108.31 (D9946)	FL1236 \$102.00 (D0216)
3347KD \$29.95 (D7971)	S539 \$13.60 (D618)	CW22 \$2.00 (D021)	W5335 \$82.87 (D2794)	WB1105 \$32.96 (D8791)						6057FB \$132.13 (D8297)	FL1236B \$127.50 (D0567)
TBA	S539 \$13.60 (D618)	CW24 \$2.00 (D021)	W6587 \$152.07 (D4219)	WB1159	TBA						

